


Shaping Your Pry Bar in the Forge

Heat Pry Bar to Forging Temperature Range



Keep Pry Bar in Forging Temperature Range



Forging Temperature Range: 850°C – 1300°C

Shape Pry Bar using Hammer and Anvil



Annealing / Normalizing: Heat Soak for 15 min, Cool Slowly

When Shaping is Complete, Anneal / Normalize in Oven – 870°C

• CC BY AmruID

• CC BY AmruID

• CC BY AmruID